



KLEFR 6923 & 6924

**KLEFR 6924** 

Hold

the right button for ≥5

seconds

to add

remove

from

the

auto-

matic

Display

Shows:

OK IN

or

OK OUT


Button scroll: press the buttons for less than 3 seconds to scroll. After 30 seconds of no interaction the meter goes back to automatic scroll mode.































for 3 seconds

to confirm.

LCD cycle time

Backlight





to confirm.

Modbus/M-bus ID

Hold both buttons for 3 seconds



Scroll with the

buttons to select

even/none/odd.

Hold both buttons Select the new for 3 seconds 4 digit password to reset. by choosing each digit (0-9).

Confirm each

Hold both buttons digit by holding for 3 seconds to confirm. both buttons for 3 seconds

Select

ON or OFF.

Hold the right button for >5seconds to enter program mode.